【参考】

ガス濃度測定結果（建物外_ガス抜き管）

GW工区
□ ガス抜き管

第2交通ターミナル
□ ガス抜き管

24年11・12月度

2025年日本国際博覧会協会

ガス濃度測定
（ガス抜き管測定点）



注）作業基準値以上の濃度を確認した場合は、当該管の周囲4か所で再測定し、作業基準値未満の安全な濃度であることを確認し作業を実施しています。

メタン(CH_4)	0.25vol%未満	：0.25vol%以上1.5vol%未満の数値の場合に着色	：1.5vol%以上の数値の場合に着色

※「over」は測定器の検知範囲（0～5vol%）以上であったことを示す。

測定点	11/1	11/2	11/4	11/5	11/6	11/7	11/8	11/9	11/11	11/12	11/13	11/14	11/15	11/16	11/18	11/19	11/20	11/21	11/22	11/23	11/25	11/26	11/27	11/28	11/29	11/30
98G2	1.00	0.25	1.20	1.05	0.30	1.35	1.50	1.55	1.25	2.30	3.65	1.50	2.10	0.75	0.65	1.30	3.15	2.40	2.85	2.10	2.60	1.75	3.75	1.95	2.10	1.05
98G7	over	over	over	over	over	over	over	2.30	over	over	over	over	over	over	over	over	over	over	over	over	over	over	over	over	over	over
00G1	0.00	1.05	0.00	0.00	0.00	0.00	0.00		0.00	0.00	0.00	0.00	2.65	0.20	0.65	0.00	0.00	0.05		0.00	0.00	0.45	0.25	0.50	0.25	0.25
00G2	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
00G3	3.75	over	3.10	1.60	0.20	0.00	0.55	1.65	2.00	2.60	0.95	1.80	over	3.60	0.60	2.30		over	1.75	2.15	0.40	3.10	4.65	2.35	1.65	1.60
01G1	1.10	0.00	4.40	1.65	0.00	1.45	2.10	over	2.10	2.20	0.00	2.65	1.65	2.25	1.05	2.00	2.45	2.60	0.60	1.15	1.10	1.60	0.00	0.00	0.00	0.00
01G2	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
01G3	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00		0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
03G1	0.00	2.65	0.00	0.60	1.40	0.00	0.00	0.00	1.75	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	3.90	over	0.00	0.00	2.10	2.35	2.50	3.65	0.55
03G2	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
03G3	0.40	1.15	0.40	0.40	0.00	0.00	0.60	0.55	0.40	0.40	0.35	0.55	0.40	0.40	0.10	0.25	0.65	0.75	1.20	0.40	0.40	0.85	0.45	0.50	0.60	0.30
03G5	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
03G6	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
07G2	over	over	0.60	0.70	over	0.00	4.40	over	over	over	over	over	0.00	over	0.00	0.00	over	over	over	0.15	over	over	over	over	over	over
08G2	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
08G3	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	over	0.00	0.00	0.00
09G1	over	over	over	over	over	over	over	over	over	2.85	over	over	over	over	over	over	over	over	over	over	over	over	0.00	over	over	over
15G1	2.75	over	3.40	1.90	0.95	2.15	0.00	0.05	0.35	over	0.00	2.50	0.25	3.50	1.85	2.65	3.90	2.40	3.35	2.55	0.00	3.80	0.90	0.65	0.00	0.35
15G2	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
15G3	1.70	over	2.40	0.50	0.90	2.60	over	1.65	over	over	3.65	over	2.80	3.70	0.85	2.85	3.40	over	2.25	3.65	1.85	over	over	2.10	0.25	3.85
18G1	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00		0.00	0.00	0.00	0.00	0.00
18G2	0.55	1.15	0.75	0.40	0.15	0.25	0.55	0.80	0.75	0.60	0.25	0.40	0.40	0.80	0.35	0.45	0.90	0.75	0.90	0.35	0.50	0.75	0.30	0.10	0.20	0.25
22G1	over	0.00	over	over	0.00	0.00	0.00	0.00	over	over	0.60	0.00	2.95	4.15	0.60	0.25	over	over	0.00	0.75	0.00	over	0.00	0.00	0.00	0.00
22G2	over	over	over	over	3.55	0.95	4.05	over	4.00	over	1.00	over	over	over	0.80	over	over	0.00	over	2.80	0.10	over	0.00	over	over	over
22G3	0.85	over	1.75	0.00	0.30	0.00	1.35	0.45	0.95	1.35	0.45	0.35	0.85	1.35	0.00	0.25	2.70	1.90	2.70	0.10	0.95	4.35	1.50	1.25	0.65	0.25
22G4	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00

注）作業基準値以上の濃度を確認した場合は、当該管の周囲4か所で再測定し、安全に作業ができる濃度であることを確認している。

一酸化炭素(CO)	50ppm以下																										
測定点	11/1	11/2	11/4	11/5	11/6	11/7	11/8	11/9	11/11	11/12	11/13	11/14	11/15	11/16	11/18	11/19	11/20	11/21	11/22	11/23	11/25	11/26	11/27	11/28	11/29	11/30
98G2	OVER	326.0	OVER	1,320.0	356.0	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	1,579.0	744.0	OVER	OVER	OVER	OVER	OVER	1,452.0	OVER	OVER	OVER	827.0	1,270.0
98G7	OVER	OVER	OVER	1,714.0	OVER	OVER	OVER	1,128.0	OVER	OVER	OVER	OVER	OVER	OVER	1,700.0	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER
00G1	79.0	OVER	12.0	0.0	6.0	0.0	0.0		0.0	0.0	0.0	0.0	10.0	101.0	0.0	6.0	0.0	8.0		43.0	0.0	1,321.0	103.0	410.0	74.0	103.0
00G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
00G3	5.0	OVER	2.0		0.0	3.0	0.0	OVER	0.0	6.0	0.0	1,096.0	0.0	0.0	0.0	6.0		19.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
01G1	580.0	50.0	834.0	545.0	0.0	1,202.0	427.0	OVER	OVER	OVER	0.0	3.0	691.0	OVER	170.0	OVER	OVER	OVER	288.0	224.0	292.0	OVER	0	0.0	0.0	0.0
01G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
01G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G1	0.0	OVER	0.0	389.0	1,270.0	0.0	0.0	0.0	OVER	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	OVER	OVER	0.0	0.0	OVER	OVER	OVER	OVER	290.0
03G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G3	119.0	482.0	204.0	440.0	50.0	90.0	325.0	229.0	178.0	229.0	207.0	348.0	185.0	145.0	63.0	164.0	187.0	278.0	452.0	176.0	147.0	242.0	188.0	153.0	171.0	116.0
03G5	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G6	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
07G2	OVER	OVER	OVER	OVER	OVER	0.0	OVER	OVER	OVER	OVER	OVER	OVER	0.0	OVER	0.0	0.0	OVER	OVER	OVER	390.0	OVER	OVER	OVER	OVER	OVER	OVER
08G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
08G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
09G1	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	0.0	OVER	OVER	OVER
15G1	OVER	OVER	1,608.0	1,020.0	479.0	OVER	0.0	0.0	129.0	OVER	0.0	OVER	83.0	OVER	1,025.0	OVER	OVER	1,360.0	OVER	OVER	0.0	OVER	520.0	357.0	15.0	177.0
15G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
15G3	OVER	OVER	OVER	OVER	1,418.0	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	1,116.0	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	435.0	OVER
18G1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		0.0	0.0	0.0	0.0	0.0
18G2	935.0	OVER	OVER	1,337.0	495.0	7.5	114.0	OVER	OVER	OVER	681.0	1,161.0	809.0	OVER	801.0	817.0	OVER	OVER	OVER	556.0	1,065.0	OVER	593.0	295.0	417.0	394.0
22G1	OVER	0.0	OVER	OVER	0.0	0.0	0.0	0.0	OVER	OVER	765.0	0.0	OVER	OVER	0.0	130.0	OVER	OVER	0.0	147.0	0.0	OVER	0.0	0.0	0.0	0.0
22G2	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	420.0	OVER	OVER	OVER	773.0	OVER	OVER	0.0	OVER	OVER	42.0	OVER	0.0	OVER	OVER	OVER
22G3	16.0	OVER	17.0	0.0	6.0	3.0	12.0	OVER	5.0	19.0	12.0	3.0	13.0	6.0	0.0	0.0	25.0	36.0	226.0	0.0	54.0	88.0	27.0	0.0	21.0	18.0
22G4	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

：50ppmを超える数値の場合に着色　※「over」は測定器の検知範囲（0～2000ppm）を超えたことを示す。

注）作業基準値以上の濃度を確認した場合は、当該管の周囲4か所で再測定し、安全に作業ができる濃度であることを確認している。

硫化水素(H_2S)	1ppm以下																										
測定点	11/1	11/2	11/4	11/5	11/6	11/7	11/8	11/9	11/11	11/12	11/13	11/14	11/15	11/16	11/18	11/19	11/20	11/21	11/22	11/23	11/25	11/26	11/27	11/28	11/29	11/30
98G2	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER
98G7	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER
00G1	0.0	OVER	8.5	8.0	0.0	0.0	1.0		0.0	0.0	0.0	0.0	OVER	0.0	1.0	0.0	0.0	0.0		0.0	0.0	OVER	0.0	OVER	0.0	OVER
00G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
00G3	OVER	OVER	OVER	1.0	0.0	0.0	1.0	OVER	1.5	OVER	0.0	OVER	OVER	OVER	0.0	0.0		OVER	0.0	0.0	0.0	OVER	OVER	1.5	0.0	0.0
01G1	OVER	0.0	OVER	OVER	1.0	OVER	OVER	OVER	OVER	OVER	0.0	OVER	OVER	OVER	OVER	OVER	OVER	2.5	OVER	OVER	OVER	OVER	0.0	0.0	0.0	0.0
01G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
01G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G1	0.0	47.0	0.0	2.0	11.0	0.0	0.0	0.0	9.5	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	9.5	41.5	0.0	0.0	3.5	7.0	6.5	7.0	0.0
03G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G3	4.0	6.5	1.5	3.0	0.0	1.5	1.5	1.5	2.0	1.0	1.0	1.5	1.0	1.0	1.0	0.0	0.0	1.0	1.0	0.0	0.0	1.0	1.0	0.0	0.0	0.0
03G5	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G6	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
07G2	50.0	50.0	15.5	17.5	50.0	0.0	50.0	50.0	50.0	50.0	50.0	50.0	0.0	50.0	0.0	0.0	50.0	50.0	50.0	1.5	50.0	50.0	50.0	50.0	50.0	50.0
08G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
08G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	OVER	0.0	0.0	0.0
09G1	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	0.0	OVER	OVER	OVER
15G1	OVER	OVER	OVER	OVER	OVER	OVER	0.0	0.0	2.5	OVER	0.0	OVER	0.0	OVER	OVER	OVER	OVER	OVER	OVER	OVER	0.0	OVER	OVER	OVER	3.5	5.0
15G2	0.0	0.0	0.0	0.0	3.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
15G3	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER
18G1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		0.0	0.0	0.0	0.0	0.0
18G2	17.0	24.5	12.0	7.0	5.5	6.5	6.5	8.5	12.5	11.0	5.0	5.0	5.0	9.0	4.0	2.5	2.5	5.0	4.5	2.5	1.5	5.5	3.5	2.0	1.5	1.5
22G1	OVER	0.0	OVER	OVER	0.0	0.0	0.0	0.0	OVER	OVER	1.0	0.0	OVER	OVER	1.0	0.0	OVER	OVER	1.0	OVER	0.0	OVER	0.0	0.0	0.0	0.0
22G2	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	0.0	OVER	OVER	OVER	OVER	0.0	OVER	OVER	OVER
22G3	OVER	OVER	OVER	0.0	OVER	0.0	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	0.0	OVER	OVER	OVER	OVER	0.0	OVER	OVER	OVER	OVER	OVER	OVER
22G4	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	OVER	0.0	0.0	0.0	0.0	0.0	0.0	0.0

：1ppmを超える数値の場合に着色　　※「over」は測定器の検知範囲（0～50ppm）を超えたことを示す。

注）作業基準値以上の濃度を確認した場合は、当該管の周囲4か所で再測定し、安全に作業ができる濃度であることを確認している。

二酸化炭素(CO_2)	1.5%以下																										
測定点	11/1	11/2	11/4	11/5	11/6	11/7	11/8	11/9	11/11	11/12	11/13	11/14	11/15	11/16	11/18	11/19	11/20	11/21	11/22	11/23	11/25	11/26	11/27	11/28	11/29	11/30
98G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
98G7	0.0	0.0	0.0	0.5	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
00G1	0.0	0.0	0.0	0.7	0.0	0.0	0.0		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		0.0	0.0	0.0	0.0	0.0	0.0	0.0
00G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
00G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
01G1	0.0	0.0	0.0	0.5	0.0	0.3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
01G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
01G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G5	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G6	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
07G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
08G2	0.0	0.0	0.0	0.3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
08G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.7	0.0	0.0	0.0
09G1	0.0	0.0	0.0	0.0	0.3	0.3	0.0	0.7	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.5	0.0	0.0	0.4	0.0	0.0	0.0	0.0	0.0	0.4	0.4
15G1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
15G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
15G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
18G1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		0.0	0.0	0.0	0.0	0.0
18G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
22G1	0.0	0.0	0.0	0.5	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
22G2	0.3	0.0	0.0	0.5	0.0	0.0	0.0	0.0	0.0	0.3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
22G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
22G4	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

：1.5%を超える数値の場合に着色　　※「over」は測定器の検知範囲（0～100%）を超えたことを示す。

注）作業基準値以上の濃度を確認した場合は、当該管の周囲4か所で再測定し、安全に作業ができる濃度であることを確認している。

アンモニア(NH_3)↑	25ppm以下	：25ppmを超える数値の場合に着色　※「over」は測定器の検知範囲（0～400ppm）を超えたことを示す。

測定点	11/1	11/2	11/4	11/5	11/6	11/7	11/8	11/9	11/11	11/12	11/13	11/14	11/15	11/16	11/18	11/19	11/20	11/21	11/22	11/23	11/25	11/26	11/27	11/28	11/29	11/30
98G2	5.1	0.9	3.4	0.0	0.0	1.7	2.6	11.1	0.0	7.7	3.4	6.0	3.4	0.9	0.0	5.1	5.1	7.7	5.7	5.1	5.1	6.8	11.1	4.3	4.3	5.1
98G7	0.9	0.0	5.1	0.9	3.4	1.7	3.4	12.8	1.7	5.1	2.6	1.7	3.4	1.7	2.6	2.6	5.1	1.7	3.4	2.6	3.4	2.6	2.6	0.0	0.0	0.0
00G1	0.0	5.1	0.0	0.0	0.0	0.0	0.0		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		0.0	0.0	0.0	0.0	0.0	0.0	1.7
00G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
00G3	0.0	10.2	1.7	0.0	0.0	0.0	2.4	17.9	0.0	10.2	0.0	0.0	0.0	0.0	3.4	0.0		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	5.1
01G1	4.3	0.9	5.1	0.0	0.0	0.0	4.3	2.6	0.0	21.3	0.0	0.0	0.0	3.4	0.0	0.0	0.0	1.7	0.0	0.0	3.4	5.1	0.0	0.0	0.0	0.0
01G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
01G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G1	0.0	6.8	0.0	0.0	0.0	0.0	0.0	0.0	0.9	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	11.1	0.0	0.0	0.0	0.0	1.7	0.9	1.7	5.1
03G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.9	0.9	0.9	1.7	1.7	0.0	0.0	0.0	0.0	0.0	2.6	0.0	2.6	0.0	0.0	0.0	0.0	0.0	0.0
03G5	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G6	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
07G2	0.0	0.0	0.0	1.7	2.6	0.0	4.3	8.5	2.6	20.4	20.4	17.9	0.0	25.5	0.0	0.0	2.6	11.9	22.1	0.0	20.4	14.5	5.1	11.9	20.4	0.0
08G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0	0.0	0.0
08G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	15.3	0	0.0	0.0
09G1	108.2	11.1	32.3	31.5	23.0	34.9	42.2	102.9	68.2	7.7	98.6	116.5	82.5	25.5	25.5	40.0	13.9	25.5	40.0	17.0	1.7	10.2	0.0	8.5	20.4	4.3
15G1	0.0	13.2	0.0	0.0	1.7	2.6	0.0	0.0	0.0	160.7	0.0	6.8	0.0	3.4	0.0	10.2	1.7	0.9	1.7	1.7	0.0	2.6	0.0	3.4	0.0	0.9
15G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
15G3	0.9	13.6	1.7	1.7	0.0	0.0	47.6	12.8	12.8	40.8	28.3	42.5	9.4	4.3	1.7	7.7	6.8	20.4	4.3	4.3	5.1	23.8	13.6	10.2	0.0	18.8
18G1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		0.0	0.0	0.0	0.0	0
18G2	2.6	1.7	1.7	0.0	1.7	0.9	1.7	0.0	2.6	1.7	1.7	1.7	0.0	1.7	0.0	1.7	3.4	0.9	1.7	0.0	0.0	1.7	0.9	0.0	1.7	1.7
22G1	3.4	0.0	5.1	5.1	0.0	0.0	0.0	0.0	3.4	25.5	0.0	0.0	11.1	0.9	0.0	0.0	7.7	6.0	0.0	0.0	0.0	17.9	0.0	0.0	0.0	0.0
22G2	1.7	5.1	8.5	4.3	4.3	0.9	4.3	6.8	2.6	9.4	0.0	3.4	10.5	6.8	0.0	6.8	6.8	0.0	7.7	5.4	1.7	16.2	0.0	7.7	0.0	5.1
22G3	0.9	7.7	0.9	0.0	0.0	0.0	0.9	0.0	0.0	19.6	0.0	0.0	0.0	0.0	0.9	0.0	0.0	0.0	2.6	0.0	0.9	0.0	0.0	0.0	3.4	0.0
22G4	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

注）作業基準値以上の濃度を確認した場合は、当該管の周囲4か所で再測定し、安全に作業ができる濃度であることを確認している。

メタン(CH_4)	0.25vol%未満		：0.25vol%以上1.5vol%未満の数値の場合に着色								：1.5vol%以上の数値の場合に着色													
測定点	※「over」は測定器の検知範囲（0～5vol%）以上であったことを示す。																							
	12/2	12/3	12/4	12/5	12/6	12/7	12/9	12/10	12/11	12/12	12/13	12/14	12/16	12/17	12/18	12/19	12/20	12/21	12/23	12/24	12/25	12/26	12/27
98G2	1.70	1.35	2.10	1.35	2.20	1.95	3.10	2.35	1.90	1.85	over	1.85	2.10	1.50	over	0.80	1.40	2.35	1.60	0.95	1.60	1.45	1.25
98G7	over	over	over	over	over	over	over	over	over	over	over	over	over	over	over	over	over	over	over	over	over	over	over
00G1	0.00	0.00	0.50	0.40	0.75	0.60	0.05	0.10	0.20	0.00	0.35	0.10	0.35	0.55	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.30	0.40
00G2	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
00G3	0.00	over	over	3.25	over	4.20	over	over	over	over	over	0.00	over	2.30	over	0.00	0.00	over	over	over	over	over	over
01G1	0.00	0.00	0.25	0.00	0.00	0.00	0.00	0.80	0.05	0.35	3.00	0.00	0.00	0.00	0.00	0.00	0.75	3.05	0.00	0.00	0.00	0.00	0.00
01G2	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
01G3	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
03G1	over	over	over	over	4.70	0.00	0.00	over	over	0.00	0.00	4.75	1.15	over	over	0.00	0.00	over	2.25	1.40	0.00	1.90	2.40
03G2	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
03G3	0.20	0.65	0.80	0.25	0.10	0.10	0.05	1.15	1.25	0.60	0.50	0.25	0.25	0.05	0.00	0.00	0.25	0.60	0.00	0.25	0.55	0.90	0.00
03G5	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
03G6	0.00	0.00		0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
07G2	over	over		over	over	over	over	over	over	over	over	0.00	over	over	over	0.00	0.00	over	2.85	over	over	over	over
08G2	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
08G3	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00		0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
09G1	over	over	over	over	4.10	over	over	over	over	over	over	over	over	over	over	1.60	over	over	over	2.05	1.45	over	over
15G1	3.85	over	1.20	0.45	0.95	0.85	3.20	3.05	1.80	1.10	1.65	0.40	0.80	2.40	over	0.00	0.75	0.00	0.00	0.00	0.00	0.00	0.35
15G2	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
15G3	over	over	1.75	2.70	2.60	4.65	3.35	over	over	0.30	over	3.35	over	1.25	2.25	0.00	4.15	2.55	1.05	2.05	over	2.00	1.25
18G1	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
18G2	0.55	0.30	0.65	0.30	0.15	0.00	0.00	0.30	0.45	0.40	0.55	0.20	0.20	0.25	0.15	0.25	0.05	0.60	0.20	0.00	0.40	0.10	0.55
22G1	0.00	0.00	over	0.00	0.00	0.00	0.00	0.00	0.00	0.00	over	0.00	0.00	over	0.00	0.00	over	over	0.00	0.00	0.00	over	0.00
22G2	3.70	over	over	over	over	over	over	over	over	0.75	over	1.85	over	over	over	0.35	over	over	over	2.05	over	over	over
22G3	1.00	1.25	3.40	0.60	1.20	0.35	0.65	1.80	1.20	0.65	over	0.00	0.30	2.15	1.10	0.00	1.50		0.45	0.45	0.50	1.75	0.00
22G4	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00

注）作業基準値以上の濃度を確認した場合は、当該管の周囲4か所で再測定し、安全に作業ができる濃度であることを確認している。

一酸化炭素(CO)	50ppm以下		：50ppmを超える数値の場合に着色　※「over」は測定器の検知範囲（0～2000ppm）を超えたことを示す																				
測定点	12/2	12/3	12/4	12/5	12/6	12/7	12/9	12/10	12/11	12/12	12/13	12/14	12/16	12/17	12/18	12/19	12/20	12/21	12/23	12/24	12/25	12/26	12/27
98G2	OVER	OVER	OVER	OVER	OVER	1,873.0	1,672.0	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	1,086.0	OVER	OVER	1,902.0	OVER	OVER	OVER	1,095.0
98G7	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER
00G1	2.0	0.0	354.0	185.0	415.0	224.0	41.0	2.0	11.0	12.0	146.0	42.0	135.0	452.0	32.0	0.0	0.0	0.0	0.0	0.0	0.0	42.0	44.0
00G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
00G3	0.0	8.0	12.0	0.0	2.0	0.0	OVER	23.0	13.0	0.0	46.0	0.0	2.0	0.0	0.0	0.0	0.0	OVER	0.0	5.0	6.0	17.0	0.0
01G1	0.0	0.0	14.0	0.0	0.0	0.0	0.0	14.0	5.0	13.0	OVER	0.0	0.0	0.0	0.0	0.0	9.0	947.0	0.0	0.0	0.0	0.0	0.0
01G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
01G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G1	OVER	OVER	OVER	OVER	OVER	0.0	0.0	OVER	OVER	0.0	0.0	OVER	593.0	OVER	OVER	0.0	0.0	OVER	1,235.0	594.0	0.0	OVER	1,542.0
03G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G3	71.0	200.0	253.0	50.0	41.0	56.0	32.0	278.0	388.0	165.0	126.0	29.0	73.0	9.0	0.0	48.0	94.0	154.0	0.0	58.0	153.0	208.0	11.0
03G5	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G6	0.0	0.0		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
07G2	OVER	OVER		OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	0.0	OVER	OVER	OVER	0.0	0.0	OVER	OVER	OVER	OVER	OVER	OVER
08G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
08G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
09G1	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER
15G1	OVER	OVER	OVER	283.0	461.0	243.0	904.0	1,851.0	OVER	362.0	1,011.0	152.0	315.0	OVER	19.0	39.0	221.0	0.0	32.0	0.0	0.0	0.0	89.0
15G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
15G3	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	600.0	OVER	OVER	OVER	357.0	OVER	27.0	OVER	OVER	OVER	OVER	OVER	OVER	OVER
18G1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
18G2	1,243.0	987.0	1,441.0	643.0	376.0	146.0	210.0	604.0	1,010.0	817.0	1,403.0	367.0	253.0	351.0	376.0	492.0	183.0	1,151.0	315.0	113.0	750.0	452.0	191.0
22G1	0.0	0.0	OVER	0.0	0.0	0.0	0.0	0.0	0.0	0.0	OVER	0.0	0.0	OVER	0.0	0.0	OVER	OVER	0.0	0.0	0.0	OVER	0.0
22G2	1,570.0	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	55.0	OVER	330.0	OVER	OVER	OVER	8.0	OVER	OVER	OVER	708.0	OVER	OVER	OVER
22G3	70.0	17.0	75.0	13.0	10.0	0.0	18.0	115.0	51.0	5.0	295.0	0.0	0.0	25.0	15.0	0.0	60.0		0.0	3.0	16.0	36.0	0.0
22G4	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

注）作業基準値以上の濃度を確認した場合は、当該管の周囲4か所で再測定し、安全に作業ができる濃度であることを確認している。

硫化水素(H_2S)	1ppm以下																							
測定点																								
	12/2	12/3	12/4	12/5	12/6	12/7	12/9	12/10	12/11	12/12	12/13	12/14	12/16	12/17	12/18	12/19	12/20	12/21	12/23	12/24	12/25	12/26	12/27
98G2	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	0.0	OVER	OVER	OVER
98G7	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER
00G1	1.0	0.0	OVER	4.0	OVER	OVER	0.0	0.0	0.0	0.0	3.0	0.0	0.0	OVER	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
00G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
00G3	0.0	OVER	OVER	0.0	OVER	1.5	OVER	OVER	OVER	OVER	OVER	0.0	OVER	OVER	OVER	0.0	OVER	OVER	OVER	OVER	OVER	OVER	0.0
01G1	0.0	0.0	OVER	0.0	0.0	0.0	0.0	OVER	2.0	0.0	OVER	0.0	0.0	0.0	0.0	0.0	OVER	OVER	0.0	0.0	0.0	0.0	0.0
01G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
01G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G1	5.0	11.0	20.0	12.5	12.0	0.0	0.0	8.5	19.4	0.0	0.0	4.0	1.0	4.5	3.0	0.0	0.0	50.0	18.5	8.0	0.0	10.5	22.5
03G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.0	0.0	1.0	0.0	0.0	0.0	1.0	0.0
03G5	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G6	0.0	0.0		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
07G2	50.0	50.0		50.0	50.0	50.0	50.0	50.0	50.0	50.0	50.0	0.0	50.0	50.0	50.0	0.0	0.0	50.0	50.0	50.0	50.0	50.0	50.0
08G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
08G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
09G1	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER
15G1	OVER	OVER	OVER	OVER	OVER	2.5	OVER	OVER	OVER	OVER	OVER	3.0	OVER	OVER	OVER	OVER	OVER	0.0	0.0	0.0	0.0	0.0	0.0
15G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
15G3	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	0.0	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	0.0	OVER	OVER	OVER	OVER
18G1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
18G2	1.0	2.0	2.5	2.0	2.0	0.0	0.0	0.0	1.0	1.0	1.0	0.0	0.0	1.0	0.0	5.0	2.5	5.0	3.0	1.0	3.0	2.0	1.5
22G1	0.0	0.0	OVER	0.0	0.0	0.0	0.0	0.0	0.0	0.0	OVER	0.0	0.0	OVER	0.0	0.0	OVER	OVER	0.0	0.0	0.0	OVER	0.0
22G2	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	0.0	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER
22G3	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	OVER	0.0	OVER	OVER	OVER	0.0	OVER		OVER	OVER	OVER	OVER	0.0
22G4	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

：1ppmを超える数値の場合に着色　　※「over」は測定器の検知範囲（0～50ppm）を超えたことを示す。

注）作業基準値以上の濃度を確認した場合は、当該管の周囲4か所で再測定し、安全に作業ができる濃度であることを確認している。

二酸化炭素(CO_2)	1.5%以下																							
測定点																								
	12/2	12/3	12/4	12/5	12/6	12/7	12/9	12/10	12/11	12/12	12/13	12/14	12/16	12/17	12/18	12/19	12/20	12/21	12/23	12/24	12/25	12/26	12/27
98G2	0.0	0.0	0.0	0.3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
98G7	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
00G1	1.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
00G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
00G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
01G1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
01G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
01G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G5	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G6	0.0	0.0		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
07G2	0.0	0.0		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
08G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
08G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
09G1	0.0	0.4	0.0	0.3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
15G1	0.0	0.3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
15G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
15G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
18G1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
18G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
22G1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
22G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
22G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		0.0	0.0	0.0	0.0	0.0
22G4	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

：1.5%を超える数値の場合に着色　※「over」は測定器の検知範囲（0～100%）を超えたことを示す。

注）作業基準値以上の濃度を確認した場合は、当該管の周囲4か所で再測定し、安全に作業ができる濃度であることを確認している。

アンモニア(NH_3)↑	25ppm以下																						
測定点																							
	12/2	12/3	12/4	12/5	12/6	12/7	12/9	12/10	12/11	12/12	12/13	12/14	12/16	12/17	12/18	12/19	12/20	12/21	12/23	12/24	12/25	12/26	12/27
98G2	7.7	5.9	2.6	12.2	3.4	5.1	3.4	11.1	5.1	5.1	16.2	2.6	6.8	7.7	12.8	0.9	3.4	9.7	1.7	0.0	5.1	0.0	1.7
98G7	0.0	0.0	0.0	0.0	13.6	0.0	0.0	0.0	0.0	0.0	0.0	0.0	22.8	4.3	2.6	0.9	4.3	0.0	0.0	0.0	0.0	0.0	0.0
00G1	0.9	0.0	0.0	0.0	0.0	0.0	0.9	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.7	0.9
00G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
00G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	23.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.9
01G1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.7	0.0	1.7	0.0	0.0	0.0	0.0	0.0	0.0	0.0	17.9	0.0	0.0	0.0	0.0	0.0
01G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
01G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G1	1.7	13.6	18.0	6.4	0.0	0.0	0.0	22.2	5.0	0.0	0.0	0.9	0.0	1.7	0.0	0.0	0.0	0.9	0.0	0.0	0.0	5.1	0.0
03G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G3	0.0	0.0	0.9	0.0	0.0	0.0	0.0	0.0	0.0	2.6	0.0	0.0	0.0	0.0	0.0	0.0	0.0	2.6	0.0	0.0	0.0	0.0	0.0
03G5	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
03G6	0.0	0.0		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
07G2	2.0	0.0		30.6	34.0	12.8	34.0	17.0	57.0	4.8	26.5	0.0	27.2	24.7	32.3	0.0	0.0	3.4	0.0	18.7	14.5	10.2	17.0
08G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
08G3	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0		0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
09G1	6.3	18.7	24.7	17.2	6.8	0.0	34.4	21.3	38.8	31.5	53.6	23.8	56.1	38.7	52.7	11.9	6.8	20.7	56.3	13.6	0.0	11.7	9.4
15G1	2.6	2.6	0.0	4.3	6.8	0.0	2.6	0.0	0.0	0.0	0.0	0.0	5.1	8.5	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.9
15G2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
15G3	25.5	15.3	0.0	4.3	1.7	5.1	1.7	9.4	17.0	0.0	23.8	0.9	25.5	0.0	8.5	0.0	13.6	0.9	0.0	0.9	13.6	0.9	0.0
18G1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
18G2	0.9	0.0	3.1	1.7	0.0	0.0	0.0	0.0	0.0	0.0	1.7	0.0	0.0	1.7	0.0	1.7	0.9	0.9	0.0	0.0	0.0	0.0	0.0
22G1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1.7	5.1	0.0	0.0	0.0	0.0	0.0
22G2	2.6	7.7	0.9	0.0	0.9	13.2	2.6	6.0	0.0	0.0	1.7	4.3	7.7	14.5	7.7	0.0	11.2	11.1	7.7	0.0	5.1	0.9	8.5
22G3	0.0	0.0	12.8	0.0	0.0	2.6	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.9	0.0	0.0		0.0	0.0	0.0	7.7	0.0
22G4	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

：25ppmを超える数値の場合に着色　※「over」は測定器の検知範囲（0～400ppm）を超えたことを示す。

注）作業基準値以上の濃度を確認した場合は、当該管の周囲4か所で再測定し、安全に作業ができる濃度であることを確認している。



【第２交通ターミナル】メタン（CH4）（vol%）

基準値：1.5vol%（30%LEL）未満（安全労働衛生規則））

爆発下限界値：5.0vol%（100%LEL）

0.25vol%未満（5～30%LEL）

0.25以上1.5vol%未満（5～30%LEL）

1.5vol%以上（30%LEL以上）

※「over」は測定器の検知範囲上限値（5vol%）以上（100%LEL）であったことを示す。

日付 / 測定点	12/24	12/25	12/26
01G5	0.25	OVER	OVER
G3-2	OVER	OVER	OVER
g2	0.50	0.55	0.55
94G2	OVER	OVER	OVER
G2-3	0.00	OVER	OVER
G2-4	0.00	0.00	0.00
G6	OVER	OVER	OVER
g	0.00	0.25	0.25
01G6	0.00	0.00	0.00
01G7	0.00	0.00	0.40
G3-1	0.00	1.10	2.70
94G1	4.35	2.75	2.75
G2-2	0.00	0.00	0.00
G5	0.00	0.00	0.00
G4	0.00	0.00	0.00
G3	0.00	0.00	0.00

注）基準値以上の濃度を確認した場合は、当該管の周囲４か所で再測定し、安全に作業ができる濃度であることを確認している。

【第２交通ターミナル】一酸化炭素（CO）（ppm）

基準値：50ppm以下（「許容濃度等の勧告」（日本産業衛生学会））

50ppm以下

50ppm超

日付 / 測定点	12/24	12/25	12/26
01G5	0.0	4.0	4.0
G3-2	0.0	2.0	2.0
g2	0.0	0.0	0.0
94G2	0.0	7.0	7.0
G2-3	7.0	15.0	15.0
G2-4	0.0	0.0	0.0
G6	2.0	2.0	2.0
g	0.0	0.0	0.0
01G6	0.0	0.0	0.0
01G7	0.0	0.0	0.0
G3-1	0.0	14.0	14.0
94G1	4.0	4.0	4.0
G2-2	0.0	0.0	0.0
G5	0.0	0.0	0.0
G4	0.0	0.0	0.0
G3	0.0	0.0	0.0

【第２交通ターミナル】硫化水素（H_2S）（ppm）

基準値：1ppm（「許容濃度等の勧告」（日本産業衛生学会））

1ppm以下

1ppm超

日付 / 測定点	12/24	12/25	12/26
01G5	0.0	0	0
G3-2	0.0	1.4	1.4
g2	0.0	0	0
94G2	0.0	0	0
G2-3	0.0	0	0
G2-4	0.0	0.0	0.0
G6	0.4	0.4	0.4
g	0.0	0.0	0.0
01G6	0.0	0.0	0.0
01G7	0.0	0.0	0.0
G3-1	0.0	0.0	0.0
94G1	0.0	3.4	3.4
G2-2	0.0	0.0	0.0
G5	0.0	0.0	0.0
G4	0.0	0.0	0.0
G3	0.0	0.0	0.0

注）
基準値以上の濃度を確認した場合は、当該管の周囲４か所で再測定し、安全に作業ができる濃度であることを確認している。

【第２交通ターミナル】二酸化炭素（CO2）（vol%）

基準値1.5vol%以下（労働安全衛生規則）

1.5vol％以下

1.5vol％超

※「over」は測定器の検知範囲上限値（1.0vol%）を超えたことを示す。

日付 / 測定点	12/24	12/25	12/26
01G5	0.8160	over	over
G3-2	0.0012	0.0028	0.0028
g2	0.0000	0.0000	0.0000
94G2	over	over	over
G2-3	0.0000	over	over
G2-4	0.0000	0.0000	0.0000
G6	over	over	over
g	0.0000	0.0000	0.0000
01G6	0.0000	0.0000	0.0000
01G7	0.0000	0.0024	0.0024
G3-1	0.0000	over	over
94G1	over	over	over
G2-2	0.0000	0.0000	0.0000
G5	0.0000	0.0000	0.0000
G4	0.0000	0.0000	0.0000
G3	over	over	over

【第２交通ターミナル】アンモニア（NH3）（ppm）

基準値：25ppm以下（「許容濃度等の勧告」（日本産業衛生学会））

25ppm以下

25ppm超

※「over」は測定器の検知範囲上限値（5,000ppm）を超えたことを示す

日付 / 測定点	12/24	12/25	12/26
01G5	over	over	over
G3-2	over	over	over
g2	over	over	over
94G2	over	over	over
G2-3	0	over	over
G2-4	0	3,090	3,090
G6	over	over	over
g	420	over	over
01G6	0	0	0
01G7	270	over	over
G3-1	0	over	over
94G1	over	over	over
G2-2	0	0	0
G5	0	0	0
G4	0	0	0
G3	265	90	85

注）
基準値以上の濃度を確認した場合は、当該管の周囲４か所で再測定し、安全に作業ができる濃度であることを確認している。